

DIGITUS Fiber Optic Multimode Patch Cord, OM4, LC / SC

DK-2532-03-4 EAN 4016032308935





FO patch cord, duplex, LC to SC MM OM4 50/125 μ , 3 m

FO patch cord, duplex, LC to SC,MM OM4 50/125 $\mu,\,3$ m

Future-oriented standards and high-end quality for your network.

- Duplex cable
- LSÖH
- Connector with ceramic ferrule
- Cable diameter 2 mm
- Single packed with test-report
- · Color: RAL 4003

Attributes


• Assortment: Fiber Optic Patch Cables


- · Boot: two-color
- · Cable diameter: 2 mm
- · Cable jacket: LSOH
- Cable type: I-VH 2G50/125μ
- Color cable: erika violet
- Connector 1: LC
- Connector 2: SC
- Fiber class: OM4
- Fiber diameter: 50/125μ
- Mode: Multimode
- · Packaging: DIGITUS Polybag
- Length: 3 m

Logistics										
	Number (pcs)	Weight (kg)	Depth (cm)	Width (cm)	Height (cm)	cm³				
Packaging Unit Carton	120	16.80	41.00	41.00	28.00	47,068.00				
Packaging Unit Inside	15	2.10	19.00	19.00	12.00	4,332.00				
Packaging Unit Single	1	0.14	17.00	17.00	1.00	289.00				
Net single without Packaging	1	0.07	15.00	15.00	1.00	0.00				


More images:

Part No.	DK-2532-03-4						
Lenght	3 m						
Cable Type Duplex MM 50/125		OM4 LSZH					
	END A	END A		END B			
Connector Type	LC	LC		SC			
Insertion Loss (dB)	0.16	0.13	0.15	0.14			
Return Loss (dB)	41.20	39.10	38.20	42.30			
Q.C.	PASS						









Safety notes

- Avoid direct contact with light sources: Fiber optic cables, especially those with active light sources such as lasers (e.g. in optical communication systems), can emit dangerous radiation that can damage
- eyes. Take care never to look directly into the light of an optical fiber, even if the light source is invisible to the naked eye.
- When working with fiber optic cables, especially during tests or when working with lasers, protective goggles should always be worn to protect
 against harmful radiation.
- When plugging and unplugging the cable, only grasp the plug and do not pull directly on the cable.
- Do not kink or crush: Fiber optic cables are sensitive to mechanical stress.
- · To protect cables from physical damage, they should be laid in special ducts or with protective materials
- Keep cable connectors clean: Fiber optic cables are sensitive to dust and dirt. Even small particles on the connectors can severely impair the signal
 quality.
- Cables should not be used in environments with extremely high or very low temperatures. Observe the product information on the maximum operating temperature of the cable
- · Check cables regularly for visible damage such as cracks, kinks or signs of wear. Defective cables should be replaced immediately.

EU responsible person

EU based economic operator ensuring the product complies with the required regulations.

ASSMANN Electronic GmbH Auf dem Schüffel 3 Lüdenscheid, Germany https://www.assmann.com info@assmann.com