

## **DIGITUS**

### DK-3901LCA-30 EAN 4016032501251



# FTTH Preterminated blow cable, Singlemode, 1 Core LC-APC to LC-APC, 30 $\mbox{m}$

Logistics						
	Number (pcs)	Weight (kg)	Depth (cm)	Width (cm)	Height (cm)	cm³
Packaging Unit Carton	40	9.32	45.00	45.00	25.00	50,625.00
Packaging Unit Inside	10	2.33	21.50	21.50	22.00	10,169.50
Packaging Unit Single	1	0.23	34.00	23.00	2.00	1,564.00
Net single without Packaging	1	0.19	19.00	19.00	3.00	0.00

#### Safety notes

- Avoid direct contact with light sources: Fiber optic cables, especially those with active light sources such as lasers (e.g. in optical communication systems), can emit dangerous radiation that can damage
- · eyes. Take care never to look directly into the light of an optical fiber, even if the light source is invisible to the naked eye.
- When working with fiber optic cables, especially during tests or when working with lasers, protective goggles should always be worn to protect
  against harmful radiation.
- · When plugging and unplugging the cable, only grasp the plug and do not pull directly on the cable.
- Do not kink or crush: Fiber optic cables are sensitive to mechanical stress.
- $\bullet \quad \text{To protect cables from physical damage, they should be laid in special ducts or with protective materials}\\$
- Keep cable connectors clean: Fiber optic cables are sensitive to dust and dirt. Even small particles on the connectors can severely impair the signal quality
- Cables should not be used in environments with extremely high or very low temperatures. Observe the product information on the maximum
  operating temperature of the cable
- · Check cables regularly for visible damage such as cracks, kinks or signs of wear. Defective cables should be replaced immediately.

### EU responsible person

EU based economic operator ensuring the product complies with the required regulations.

ASSMANN Electronic GmbH Auf dem Schüffel 3 Lüdenscheid, Germany https://www.assmann.com info@assmann.com